

S-CAT 6020

OMA Test Cases (FUMO SCOMO)

setcom Option	OMA ETS Requirement	Description	Available	Manufacturer Verified with
---------------	---------------------	-------------	-----------	----------------------------

SA-P8082 (DM TC2)	FUMO-1.0-int-001	GSM-BTR-1-9900 FUMO Support - Verification of Tree structure for ../x*	✓	4
	FUMO-1.0-int-002	GSM-BTR-1-9900 FUMO Support - Verification of Tree structure for ../x*/Download	✓	3
	FUMO-1.0-int-003	GSM-BTR-1-9900 FUMO Support - Verification of Tree structure for ../x*/Update	✓	3
	FUMO-1.0-int-004	GSM-BTR-1-9900 FUMO Support - Verification of Tree structure for ../x*/DownloadAndUpdate	✓	4
	FUMO-1.0-int-005	GSM-BTR-1-9900 FUMO Support - Verification of GET access on ../x*/State	✓	4
	FUMO-1.0-int-006	GSM-BTR-1-9900 Successful Firmware Update using OMA-DM Large Object and EXEC on ../x*/Update Node	✓	2
	FUMO-1.0-int-007	GSM-BTR-1-9900 Successful Firmware Update using Alternative Download Mechanism and EXEC on ../x*/Update node	✓	3
	FUMO-1.0-int-008	GSM-BTR-1-9900 Successful Firmware Update using Alternative Download Mechanism and EXEC on ../x*/DownloadAndUpdate node	✓	4
	FUMO-1.0-int-009	GSM-BTR-1-9900 Downloading an Update Package using OMA-DM Large Object and EXEC on ../x*/Update Node	✓	3
	FUMO-1.0-int-013	GSM-BTR-1-9900 Failed Download due to Malformed or Bad URL	✓	4
	FUMO-1.0-int-014	GSM-BTR-1-9900 Failed download due to missing Update packages	✓	4
	FUMO-1.0-int-015	GSM-BTR-1-9900 Failure due to Incomplete Download – OMA-DM protocol	✓	0
	FUMO-1.0-int-016	GSM-BTR-1-9900 Failure due to Incomplete Download – Alternate Download	✓	0
	FUMO-1.0-int-017	GSM-BTR-1-9900 Failure due to Corrupted Update Package Downloaded	✓	4
	FUMO-1.0-int-018	GSM-BTR-1-9900 Client Initiated Firmware Update – Device Initiated Alert	✓	0

S-CAT 6020

OMA Test Cases (FUMO SCOMO)

setcom Option	OMA ETS Requirement	Description	Available	Manufacturer Verified with
	FUMO-1.0-int-019	GSM-BTR-1-9900 Client Initiated Firmware Update – User Initiated Alert	✓	2
	16	Total Test Cases in option	16	

SA-P8085 (DM TC5)	SCOMO-1.0-int-001	Verification of Tree Structure	✓	2
	SCOMO-1.0-int-002	Delivery and install using Large Object (Synchronous Report)	✓	1
	SCOMO-1.0-int-003	Delivery and install using Large Object (Asynchronous Report)	✓	0
	SCOMO-1.0-int-004	Delivery using Alternate Download (Synchronous Report)	✓	0
	SCOMO-1.0-int-005	Delivery using Alternate Download (Asynchronous Report)	✓	1
	SCOMO-1.0-int-006	Remove Software Component (Synchronous Report)	✓	1
	SCOMO-1.0-int-007	Remove Software Component (Asynchronous Report)	✓	0
	SCOMO-1.0-int-008	Activate Software Component (Synchronous Report)	✓	1
	SCOMO-1.0-int-009	Activate Software Component (Asynchronous Report)	✓	0
	SCOMO-1.0-int-010	Deactivate Software Component (Synchronous Report)	✓	1
	SCOMO-1.0-int-011	Deactivate Software Component (Asynchronous Report)	✓	0
	SCOMO-1.0-int-012	Remove Delivery Package (Synchronous Report)	✓	1
	SCOMO-1.0-int-013	Remove Delivery Package (Asynchronous Report)	✓	0
	SCOMO-1.0-int-014	Download Delivery Package (Large Object)	✓	1
	14	Total Test Cases in option	14	